COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR73ZXW

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55901
Cap Code	MXD920LW509DTM2 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£10,400.00
Reg. date	16/10/2023	**Colour**	WHITE	**CAP Average**	£9,625.00
Year	2023	**VIN**	LSH14J7C0PA822462	**CAP Below**	£8,275.00
Mileage	44,709 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking


Photos









SAIC MAXUS Automotive Co.,Ltd.
e4*2018/858*00074
LSH14J7C0PA822462
3500 kg
6000 kg
1- 1950 kg
2- 1900 kg





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door osf
Dented
Over 30mm



4: Sill os
Rusted
Over 5mm



5: Badgedecal Rear
Missing
Replace



6: Tailgate
Dented
With Paint Damage



7: Qtr Panel nsr
Rusted
Over 5mm



8: Sill ns
Rusted
Over 5mm

Interior

Carpet Condition	Average	**Upholstery Condition**	-
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK