COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FT73RRX

Ford Transit 350 2.0 ECOBLUE 170PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45237
Cap Code	FOTR20L7TRMDTM2 5 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£17,400.00
Reg. date	22/01/2024	**Colour**	WHITE	**CAP Average**	£16,400.00
Year	2024	**VIN**	WF0CXXTTRCPY77759	**CAP Below**	£14,400.00
Mileage	63,067 Miles Not Warranted	**Body Style**	Tipper	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	21/01/2027	**Gears**	6

OUTSTANDING RECALL, PASSENGER WINDOW SWITCH INOP AD BLUE, TOW BAR

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Front parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag

Photos















HIGHWAY MAINTENANCE
FT73 RRX


UK
NI
TRANSIT
BASE
2.0 I HPCR Pethrol Diesel
170 PS
Stage 6.2
350L
BLRA
0.50
FORD
e1*2007/46*1096
WF0CXXTTRCPY77759
3500
5650
1850
2450
W(mm)
L(mm)
a(mm)
B
3954
FED


Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm




3: Wheel nsf
Corroded
Light



4: Wing nsf
Chipped
Over 5mm



5: A Post ns
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Door nsf
Dented
Over 30mm



9: Door nsf
Chipped
Edge Chip



10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Door nsr
Chipped
Over 5mm



12: D Post ns
Dented
With Paint Damage



13: Wheel nsr
Corroded
Light



14: Wheel osr
Corroded
Light



15: Door osr
Chipped
Over 5mm



16: D Post os
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
Over 5mm



18: Door osf
Dented
Over 30mm



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Handle Outer osf
Scratched (Painted)
UpTo 25mm Not Thru Paint



21: Wheel osf
Corroded
Light



22: Door osf
Chipped
Over 5mm



23: Bonnet
Chipped
Over 5mm



24: Number Plate Front
Broken
Replace



25: Bumper Front
Scratched
Over 100mm Thru Paint



26: Roof
Chipped
Over 5mm



27: Seat Base Cover osf
Torn
Over 3mm



28: Seat Base Cover nsf
Soiled
Light

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK