COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR73ZXN

Maxus Deliver 9 D20 2.0 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55901
Cap Code	MXD920LW509DTM2 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£10,850.00
Reg. date	16/10/2023	**Colour**	WHITE	**CAP Average**	£10,050.00
Year	2023	**VIN**	LSH14J7CXPA822453	**CAP Below**	£8,625.00
Mileage	37,094 Miles Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

WARNING LIGHTS ON DASH, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Radio/CD
- Drivers airbag
- Cruise control
- USB/iPod interface
- Passenger airbag
- Rear parking sensor
- Air conditioning
- Central locking
- Auxiliary input socket
- Front electric windows
- Cloth seat trim

Photos
















SAIC MAXUS Automotive Co.,Ltd.
e4*2018/858*00074
LSH14J7CXPA822453
3500 kg
6000 kg
1- 1950 kg
2- 1900 kg





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front
Cracked
Over 25mm



4: Bumper Front
Insecure
Action Required



5: Door Mirror Assy nsf
Broken
Replace



6: Fuel Flap
Cracked
Replace




7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Door osr
Chipped
Multiple Chips



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: B Post os
Chipped
Multiple Chips



12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Carpets Front
Holed
Over 3mm



14: Dash Warning Lights
Displayed
No Action



15: Fascia Trim
Missing
Replace

Interior

Carpet Condition	Poor	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK		