COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR73ZYC

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55901
Cap Code	MXD920LW509DTM2 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£10,250.00
Reg. date	12/10/2023	**Colour**	WHITE	**CAP Average**	£9,525.00
Year	2023	**VIN**	LSH14J7CXPA822470	**CAP Below**	£8,175.00
Mileage	46,113 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	13/10/2027	**Gears**	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos













SAIC MAXUS Automotive Co.,L
e4*2018/858*00074
LSH14J7CXPA822470
3500 kg
6000 kg
1- 1950 kg
2- 1900 kg









Condition Check



Damage Photos



1: Wing Front Arch Extension os
Broken
Replace



2: Wing osf
Dented
With Paint Damage



3: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



4: Bonnet
Scratched
UpTo 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Door nsr
Scratched
UpTo 25mm Thru Paint



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
UpTo 100mm



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Dented
With Paint Damage



10: Door Moulding nsr
Scuffed (Unpainted)
UpTo 100mm



11: Door Moulding osr
Broken
Replace



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Door osf
Dented
With Paint Damage



15: Door osf
Chipped
Edge Chip



16: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK