COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR73ZXL

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55901
Cap Code	MXD920LW509DTM2 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£11,200.00
Reg. date	23/10/2023	**Colour**	WHITE	**CAP Average**	£10,400.00
Year	2023	**VIN**	LSH14J7CXPA822503	**CAP Below**	£8,925.00
Mileage	31,610 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Photos











SAIC MAXUS Automotive Co.,Ltd.
e4*2018/858*00074
LSH14J7CXPA822503
3500 kg
6000 kg
1- 1950 kg
2- 1900 kg










Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door osf
Dented
With Paint Damage



3: Wheel Trim osf
Broken
Replace



4: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



5: Bumper Rear
Cracked
Over 25mm



6: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK