COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR73ZYJ

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55901
Cap Code	MXD920LW509DTM2 L

Details

Location	Doncaster	**GVW**	3500kg	**CAP Clean**	£10,250.00
Reg. date	12/10/2023	**Colour**	WHITE	**CAP Average**	£9,525.00
Year	2023	**VIN**	LSH14J7C6PA822501	**CAP Below**	£8,175.00
Mileage	46,479 Miles Not Warranted	**Body Style**	Panel Van LWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	11/10/2027	**Gears**	6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Rear parking sensor
- Air conditioning
- Front electric windows


Photos















SAIC MAXUS Automotive Co.,Ltd.
e4*2018/858*00074
LSH14J7C6PA822501
3500 kg
6000 kg
1- 1950 kg
2- 1900 kg




Driver Seatbelt Not Fasten





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsr
Dented
Between 10mm + 30mm



6: Door nsr
Dented
Over 30mm



7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Dented
Between 10mm + 30mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Badgedecal Rear
Broken
Replace



13: Bumper Rear
Cracked
UpTo 25mm



14: Bumper Rear Moulding
Broken
Replace



15: Door nsr
Dented
Between 10mm + 30mm



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



18: Wing osf
Dented
With Paint Damage



19: Door osf
Dented
With Paint Damage



20: Qtr Panel osr
Dented
With Paint Damage




21: Door osf
Dented
Between 10mm + 30mm



22: Door osf
Chipped
Edge Chip



23: Carpets Front
Holed
Over 3mm



24: Seat Base Cover osf
Scuffed
UpTo 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK