COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**BX17XDC**

## Iveco Daily 70-180

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Present |
| **Cap Code** | 999900 |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Doncaster | **Colour** | WHITE | **MOT Due** | 31/07/2027 |
| **Reg. date** | 20/03/2017 | **VIN** | ZCFC270D105140279 | **Cab Type** | DAY CAB |
| **Year** | 2017 | **Body Style** | Panel Van | **Gearbox** | MANUAL |
| **Mileage** | 134,852 Km Warranted | **Service history** | Yes | **Axle Combi** | 4x2 |
| **Fuel Type** | DIESEL | **Service documents** | Printout | **Rear Suspension** | Steel |
| **GVW** | 7000kg | **Last service date** | 11/05/2026 | | |

### Tyres

| | | | | |
|---|---|---|---|---|
| **NSF** | **NSI1** | **NSI2** | **NSI3** | **NSI4** |
| **OSF** | **OSI1** | **OSI2** | **OSI3** | **OSI4** |
| **Spare** | **NSO1** | **NSO2** | **NSO3** | **NSO4** |
| | **OSO1** | **OSO2** | **OSO3** | **OSO4** |

## Features

- Bluetooth connection
- Drivers airbag
- Cruise control
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

## Photos






















13:00 0km/h
134852.2km
OK


Plating Certificate.
IVECO /70C18
RIGID
20/03/17
2017
7224
2174
7000
7000
2500
2500
225/75-16
121/120
5350
5350
225/75-16
121/120


IVECO SPA
ZCFC270D105140279
7000 kg
10500
2500
5150 kg
Type 150CC2RA
Wheelbase 4100
Engine type F1CFL411W
0,520









DANGER
ROTATING
MACHINER





# Condition Check





## Damage Photos

No Image


1: Bonnet
Chipped
Multiple Chips

No Image


2: A Post ns
Missing
Replace





3: Wing nsf
Dented
With Paint Damage





4: Door nsf
Chipped
Multiple Chips





5: Qtr Panel nsr
Chipped
Multiple Chips





6: Qtr Panel nsr
Chipped
Over 5mm





7: Qtr Panel nsr
Chipped
Over 5mm





8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint





9: Qtr Panel nsr
Rusted
Over 5mm





10: Door osr
Rusted
Over 5mm





11: Qtr Panel osr
Chipped
Multiple Chips





12: Qtr Panel osr
Chipped
Multiple Chips





13: Qtr Panel osr
Chipped
Over 5mm





14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




15: Door osf
Scratched
UpTo 25mm Thru Paint




16: Seat Base Cover osf
Torn
UpTo 3mm




17: Seat Base Cover nsf
Scuffed
Over 25mm

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Poor | **Odour** | - |

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| | | Steering | OK |

**Commercial Vehicle Auctions Limited**