COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK71UVP

Man TGL 12.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	12000kg	**MOT Due**	28/02/2027
Reg. date	14/10/2021	**Colour**	YELLOW	**Cab Type**	CREW CAB
Year	2021	**VIN**	WMA14DZZ9MY431884	**Gearbox**	AUTOMATIC
Mileage	477,073 Km Warranted	**Body Style**	Recovery	**Axle Combi**	4x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

BONIFACE STVLA+SCL DEMOUNT SLIDE BODY (YEAR 2021), C/W REMOTE, SPEC LIFT, SLIDING WINCH, DYNA CYCLE, 3POINT SEAT BELTS, UNDERSEAT STORAGE

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features



- Bluetooth connection
- Front electric windows
- Cruise control
- Central locking
- Digital radio
- Cloth seat trim
- Air conditioning

Photos








RIO
SE5000 connekt
LITE-wire
PULSE

MODE
D
R
N


MANTOL
Replacement


MAN Truck & Bus SE



DK71 UVP







SAFE WORKING LOAD OF
WINCH AND CABLE = 3500Kg








MODEL: 5T VLA + SCL
SERIAL No.: 08-20464-21
BUILD SHEET: 20464
TEST No. 3671
DATE: 20:08:2021
RATING TEST
BED (UDL) 5000 6400
SECOND CAR LIFT 2000 2500


BONIFACE








KOOK





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm




4: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



5: Door osf
Scratched
Over 25mm Thru Paint



6: Screen Front
Cracked
Replace



7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK