COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BF70NRL

Iveco Daily 35-120

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38809
Cap Code	IVDA23S352VDTM2 4 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£5,275.00
Reg. date	29/01/2021	**Colour**	WHITE	**CAP Average**	£4,600.00
Year	2021	**VIN**	ZCFC3358405383649	**CAP Below**	£3,675.00
Mileage	65,054 Miles Warranted	**Body Style**	Panel Van MWB	**Gearbox**	MANUAL
		MOT Due	15/10/2027	**Gears**	6
Fuel Type	DIESEL				

WARNING LIGHT ON DASH AIR COMPRESSOR EQUIPMENT & 110V OUTLETS, E/MIRRORS, 3520 WB

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos








BF70 NRL


IVECO
IVECO SPA
ITALY
3500 kg
7000
1900
2240 kg
Type
Wheelbase 3520
Engine type F1AGL411X
0 515








BF70 NRL
BF70 NRL










Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Bumper Rear
Dented
Between 10mm + 30mm



8: Qtr Panel osr
Dented
With Paint Damage



9: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



10: Flasher Side Repeater os
Broken
Replace



11: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK