COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GA71NET

Mercedes-Benz Vito 116 CDI Premium

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	48642
Cap Code	MEVI2016R2VDTA2 6 L

Details

Location	Doncaster	**GVW**	2800kg	**CAP Clean**	£9,375.00
Reg. date	24/05/2022	**Colour**	GREY	**CAP Average**	£8,500.00
Year	2022	**VIN**	W1V44760323984998	**CAP Below**	£7,150.00
Mileage	135,397 Miles Warranted	**Body Style**	Crew Van L2	**Gearbox**	AUTOMATIC
		MOT Due	16/06/2027	**Gears**	9
Fuel Type	DIESEL				

WARNING LIGHTS ON DASH TWIN SIDE LOAD DOOR, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Auxiliary input socket
- Passenger airbag
- Cruise control
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos
















13:36
0km/h
5641.1
mi
135397
11.0°C
R
N
D


R
N
D


MERCEDES-BENZ AG
e1*2007/46*0458
Mercedes-Benz
W1V44760323984998
3050 kg
5050 kg
1- 1550 kg
2- 1650 kg
TYP: 639/4
7992
1.0 %
0,41

































Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Number Plate Front
Missing
Replace



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door nsf
Dented
With Paint Damage



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Dented
With Paint Damage



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
Over 30mm



10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Door nsr
Dented
With Paint Damage



12: Number Plate Rear
Missing
Replace



13: Door osr
Dented
With Paint Damage



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Dented
With Paint Damage



16: Door osf
Dented
With Paint Damage



17: Door Mirror Assy osf
Broken
Replace



18: Seat Base Cover nsr
Soiled
Heavy



19: Seat Base Cover osr
Soiled
Heavy



20: Seat Base Cover nsf
Soiled
Heavy



21: Seat Base Cover osf
Holed
Over 3mm



22: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK