Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

VEHICLE INSPECTION REPORT

YT16VHJ

Ford Transit Custom 290 2.2 TDCI 100PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	25446
Cap Code	FOTU229S1 VDTM2 L

Details

Location	Bedford	**GVW**	2900kg	**CAP Clean**	£2,825.00
Reg. date	04/03/2016	**Colour**	WHITE	**CAP Average**	£2,325.00
Year	2016	**VIN**	WF0YXXTTGYFU00894	**CAP Below**	£1,650.00
Mileage	128,625 Miles Not Warranted	**Body Style**	Panel Van L1	**Gearbox**	MANUAL
		MOT Due	07/03/2027	**Gears**	6
Fuel Type	DIESEL				

WARNING LIGHT ON DASH SIDE LOADING DOOR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos









FORD
e1*2007/46*1005
WF0YXXTTGYFU00894
DRFF
0.51
3CB B
GZ R
AA G
V6
2900
4400
1550
1575
CUSTOM
BASE
GLOBAL PUMA 2.2 (D) (Diesel)
100PS
290S
STG 5
W(mm)
L(mm)
a(mm)
A
2933
FCC



230v
OUTPUT
LOAD
WARNING!
SYSTEM OVERLOADING

230v





0°C
52 mls
120625mls







Condition Check



Damage Photos



1: A Post os
Chipped
1 To 5



2: Bonnet
Dented
With Paint Damage



3: Roof
Rusted
Over 5mm



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm




5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Door osr
Scratched
UpTo 25mm Thru Paint



8: Door osf
Dented
With Paint Damage



9: Door osf
Scratched
UpTo 25mm Thru Paint



10: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault