COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BX17XBB

Iveco Daily 50-150

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	**Colour**	WHITE	**Cab Type**	DAY CAB
Reg. date	14/03/2017	**VIN**	ZCFC150B805144609	**Gearbox**	MANUAL
Year	2017	**Body Style**	Access Platform	**Axle Combi**	4x2
Mileage	147,558 Km Warranted	**Service history**	Yes	**Rear Suspension**	Steel
Fuel Type	DIESEL	**Last service date**	29/06/2026		
GVW	5200kg	**MOT Due**	30/04/2027		

VERSALIFT ETM-38-F PLATFORM

Tyres


NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**


Features

- Park assist camera

Photos










0km/h
147558.7km







VERSALIFT DISTRIBUTORS (UK) LTD
STAGE OF BUILD. STAGE 2
VIN No. ZCFC150B805144609
IVECO SPA
ZCFC150B805144609
5209 kg
8700
1- 2100
2- 3700 kg
Type IS56CC2BA
Wheelbase 3520
Engine type F1CGL411A
Engine power kW 110











EXTERNAL




BRIGADE









SWL 200 Kg







Condition Check



Damage Photos



1: Front TowEye Cvr
Missing
Replace



2: Wing osf
Dented
With Paint Damage



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Panel Front
Scratched
UpTo 25mm Not Thru Paint



5: Bonnet
Chipped
Multiple Chips



6: Screen Front
Chipped
Over 10mm




7: Panel Front
Scratched
UpTo 25mm Thru Paint



8: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



9: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



10: Door nsf
Chipped
Over 5mm



11: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



13: Door nsr
Dented
With Paint Damage



14: Door osr
Dented
Between 10mm + 30mm



15: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



16: Door osf
Chipped
Edge Chip



17: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK