COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HN64DAO

Ford Transit 460 2.2 TDCI 125PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	30742
Cap Code	FOTR22LH72UDTM2 4 L

Details

Location	Bedford	**GVW**	4600kg	**CAP Clean**	£4,950.00
Reg. date	18/11/2014	**Colour**	WHITE	**CAP Average**	£3,900.00
Year	2014	**VIN**	WF0HXXTTGHER07995	**CAP Below**	£2,650.00
Mileage	152,267 Km Not Warranted	**Body Style**	Minibus	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	04/10/2027		


WARNING LIGHT ON DASH, MILEAGE ONLY DISPLAYING ON TACHO 16 SEATS PLUS DRIVER, AD BLUE, SIDE LOADING DOOR

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Photos







VDO
13:55 0km/h
152267.7km
1
2






FORD
e11*2007/46*0807
WF0HXXTTGHER07995
TRANSIT
BASE
USR6
ST6 6
4600 kg
5350 kg
1850 kg
3120 kg
W(mm) 2126 L(mm) 6704 a(mm)
D 3750 FBD





















Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



6: Wing nsf
Dented
Between 10mm + 30mm



7: Panel Front
Dented
Between 10mm + 30mm



8: Wing osf
Dented
With Paint Damage



9: Bumper Front
Insecure
Action Required



10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Door nsf
Scratched
UpTo 25mm Thru Paint



12: Door Moulding nsr
Scuffed (Unpainted)
Over 100mm



13: Door nsr
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
Over 100mm



16: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



17: Door osr
Dented
With Paint Damage



18: Door nsr
Dented
Between 10mm + 30mm



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



20: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK