COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23XDA

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	MXD920L150HDTM2 L

Details

Location	Doncaster	**Fuel Type**	DIESEL	**Body Style**	Fridge Van LWB
Reg. date	15/06/2023	**GVW**	3500kg	**MOT Due**	18/06/2027
Year	2023	**Colour**	WHITE	**Gearbox**	MANUAL
Mileage	49,803 Miles Not Warranted	**VIN**	LSH14J7C0PA087045	**Gears**	6

THERMOKING V200-MAX UNIT, STANDBY PLUG, E/MIRRORS, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag



Photos















18%
Vehicle Speed
0 mph
48803mi


SAIC MAXUS Automotive Co.,Ltd.
e4*2018/858*00074
LSH14J7C0PA087045
3500 kg
6000 kg
1. 1950 kg
2. 1900 kg




AIRBAG








Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Qtr Panel nsr
Dented
Over 30mm



10: Badgedecal Rear
Broken
Replace




11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
Multiple Chips



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



16: Door osf
Dented
With Paint Damage



17: Screen Front
Chipped
Over 10mm



18: Door Pad osf
Soiled
Heavy



19: Carpets Front
Holed
Over 3mm



20: Seat Base Cover osf
Soiled
Heavy



21: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK