COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FN68GXS

Daf LF 150

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Reg. date	26/10/2018	**VIN**	XLRAEL1500L480953	**Axle Combi**	4x2
Year	2018	**Body Style**	Box Van	**Rear Suspension**	Steel
Mileage	312,371 Km Not Warranted	**Service history**	None	**Rear Doors**	Roller
Fuel Type	DIESEL	**MOT Due**	30/04/2027	**Tail Lift**	Tuckaway
GVW	7500kg	**Cab Type**	SLEEPER CAB		

PASSENGER DOOR INOP

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Central locking
- Cruise control
- Cloth seat trim
- Digital radio
- Front electric windows

Photos





0km/h
2372.0km
OK

R
N
D

DAF TRUCKS N.V.
DAF



12'4" (3.8m)

CHASSIS No.:
L480953
BUILD DATE:
23/10/18
DAF

150

EMERGENCY FREEPHONE No 0800 443334

DEL
RAISE
LOWER

Condition Check



Damage Photos

1: Panel Front
Chipped
Multiple Chips

2: Panel Front
Missing
Replace

3: Wing nsf
Cracked
Replace

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

5: Qtr Panel osr
Scratched
Over 25mm Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

7: Screen Front
Cracked
Replace

8: Door Pad osf
Soiled
Heavy

9: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	Poor	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK