COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23WZS

Maxus Deliver 3 90kW 50.2kWh

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	55904
Cap Code	MXD300SW92VE A2 L

Details

Location	Bedford	**GVW**	2525kg	**CAP Clean**	£4,800.00
Reg. date	26/05/2023	**Colour**	WHITE	**CAP Average**	£4,450.00
Year	2023	**VIN**	LSH14C4C5NA139542	**CAP Below**	£3,825.00
Mileage	55,910 Miles Not Warranted	**Body Style**	Fridge Van L1	**Gearbox**	AUTOMATIC
		MOT Due	25/05/2027	**Gears**	1
Fuel Type	Electric				

SIDE LOADING DOOR, THERMOKING B-100 UNIT, STANDY PLUG

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning



Photos

















SAIC MAXUS Automotive Co.,
e4*2007/46*1535
LSH14C4C5NA139542
2525 kg
2750 kg
1- 1180 kg
2- 1460 kg





THERMO KING
B-100 MAX



Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Door nsr
Scratched
Over 25mm Not Thru Paint




5: Door nsr
Dented
With Paint Damage



6: Door osr
Dented
Over 30mm



7: Bumper Rear
Cracked
Over 25mm



8: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



9: Seat Base Cover osf
Holed
Over 3mm



10: Bonnet
Chipped
Edge Chip

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK