COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23WZL

Maxus Deliver 3 90kW 50.2kWh

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	MXD300SW92VE A2 L

Details

Location	Bedford	**GVW**	2525kg	**CAP Average**	£5.00
Reg. date	26/05/2023	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2023	**VIN**	LSH14C4C2NA139613	**Gears**	1
Mileage	41,879 Miles Not Warranted	**Body Style**	Fridge Van L1		
Fuel Type	Electric	**MOT Due**	02/06/2027		

SIDE LOADING DOOR, THERMOKING B-100 UNIT, STANDY PLUG

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos









THERMO KING
B-100 MAX






SAIC MAXUS Automotive Co.,
e4*2007/46*1535
LSH14C4C2NA139613
2525 kg
2750 kg
1- 1180 kg
2- 1460 kg
















Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
UpTo 25mm Thru Paint



3: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wing Front Arch Extension ns
Broken
Replace



6: Flasher Side Repeater ns
Broken
Replace



7: Qtr Panel nsr
Dented
With Paint Damage



8: Door nsr
Dented
Between 10mm + 30mm



9: Bumper Rear
Scratched
Up To 25mm Not Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK