COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**LR23WZM**

## Maxus Deliver 3 90KW 50.2KWH

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Plus VAT |
| **V5** | Buyer To Apply |
| **Cap Id** | 55904 |
| **Cap Code** | MXD300SW92VE A2 L |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Location** | Bedford | **GVW** | 2525kg | **CAP Clean** | £4,925.00 |
| **Reg. date** | 26/05/2023 | **Colour** | WHITE | **CAP Average** | £4,575.00 |
| **Year** | 2023 | **VIN** | LSH14C4C2NA139594 | **CAP Below** | £3,925.00 |
| **Mileage** | 51,429 Miles Not Warranted | **Body Style** | Fridge Van L1 | **Gearbox** | AUTOMATIC |
| | | **MOT Due** | 07/06/2027 | **Gears** | 1 |
| **Fuel Type** | Electric | | | | |

*WARNING LIGHT ON DASH* SIDE LOADING DOOR, THERMOKING B-100 UNIT, STANDY PLUG, CHARGING CABLES PRESENT

### Tyres


| | |
|---|---|
| **NSF** | |
| **NSR** | |
| **OSF** | |
| **OSR** | |
| **Spare** | |

## Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

## Photos












THERMO KING
B-100 MAX



SAIC MAXUS Automotive Co.
e4*2007/46*1535
LSH14C4C2NA139594
2525 kg
2750 kg
1- 1180 kg
2- 1460 kg










# Condition Check




## Damage Photos



1: Wing osf
Scratched
UpTo 25mm Not Thru Paint



2: Bonnet
Chipped
Edge Chip



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



4: Door nsf
Dented
With Paint Damage



5: Door nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsr
Dented
Over 30mm



10: Door osr
Dented
Over 30mm



11: Door osr
Dented
Over 2 UpTo 10mm



12: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



13: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint



14: Switches And Controls
Broken
Replace

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |