COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LR23WZP

Maxus Deliver 3 90KW 50.2KWH

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	MXD300SW92VE A2 L

Details

Location	Bedford	**Fuel Type**	Electric	**Body Style**	Fridge Van L1
Reg. date	26/05/2023	**GVW**	2525kg	**MOT Due**	26/05/2027
Year	2023	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Mileage	45,957 Miles Not Warranted	**VIN**	LSH14C4C1NA140123	**Gears**	1

CHARGING CABLES PRESENT, SIDE LOADING DOOR, THERMOKING B-100 UNIT, STANDY PLUG, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos











THERMO KING



SAIC MAXUS Automotive Co.,Ltd.
ø4*2007/46*1535
LSH14C4C1NA140123
2525 kg
2750 kg
1- 1180 kg
2- 1460 kg








WESTLAKE


Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Bonnet
Chipped
Edge Chip



3: Bonnet
Chipped
Edge Chip



4: Bumper Front
Scratched
UpTo 25mm Thru Paint



5: Bonnet
Scratched
Over 25mm Thru Paint



6: Panel Front
Cracked
Replace



7: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



8: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



9: Wing Front Arch Extension ns
Broken
Replace



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Door nsr
Dented
With Paint Damage



12: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



13: Lamp nsr
Broken
Replace



14: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



15: Door nsr
Dented
Over 30mm



16: Tailgate
Dented
Over 2 UpTo 10mm



17: Lamp osr
Broken
Replace



18: Qtr Panel osr
Dented
Between 10mm + 30mm



19: Qtr Panel osr
Dented
Between 10mm + 30mm



20: Door osf
Poor Previous Repair
Poor Colour



21: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



22: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK