COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WU18BXN

Scania S 500

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Cab Type**	HIGHLINE CAB
Reg. date	06/03/2018	**Colour**	SILVER	**Gearbox**	AUTOMATIC
Year	2018	**VIN**	YS2S6X20009234010	**Axle Combi**	6x2
Mileage	924,722 Km Not Warranted	**Body Style**	Tractor Unit	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	31/08/2027		

WARNING LIGHT ON DASH REAR LIFT

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Front electric windows
- Leather seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos


















000km/h
0924722.8km
OK




13

SCANIA
e4*2007/46*1130
YS2S6X20009234010
(GB)
26000
44000
8000
11500
7500
27000
70000
8000
11500
7500
CS32H
9234010
E4-28R-030117
1516942
9234010
1346692
S 500 A6x2NA
FRANCE










Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Door nsf
Chipped
1 To 5



4: Door osf
Chipped
1 To 5



5: Door osf
Scratched
Over 25mm Thru Paint



6: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Turbo Boosting	OK		
Parking Brake	OK		
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK

Commercial Vehicle Auctions Limited