COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

KX17RCO

Scania R 450

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	999900

Details

Location	Doncaster	**GVW**	44000kg	**Cab Type**	HIGHLINE CAB
Reg. date	25/04/2017	**Colour**	WHITE	**Gearbox**	AUTOMATIC
Year	2017	**VIN**	YS2R6X20009222474	**Axle Combi**	6x2
Mileage	1,676,508 Miles Not Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
		MOT Due	31/05/2027	**Rear Suspension**	Air
Fuel Type	DIESEL				

DISCREPANCY ON MOT HISTORY SURROUND CAMERA SYSTEM, SLIDING 5TH WHEEL


Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Photos








































Commercial Vehicle Auctions Limited

Condition Check



Damage Photos



1: Wing osf
Poor Previous Repair
Poor Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front
Cracked
UpTo 25mm



5: Bumper Front
Cracked
UpTo 25mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



10: Wing Front Arch Extension ns
Broken
Replace



11: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



12: Qtr Panel osr
Cracked
Replace



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osf
Chipped
Edge Chip



16: Qtr Panel osr
Rusted
Over 5mm



17: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



18: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK