COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MX72VTN

Ford Transit 2.0 EcoBlue 130PS LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45297
Cap Code	FOTR2035331DTM2 5 L

Details

Location	Livingston	**GVW**	3500kg	**CAP Clean**	£15,600.00
Reg. date	19/10/2022	**Colour**	WHITE	**CAP Average**	£14,200.00
Year	2022	**VIN**	WF0CXXTTRCNL20558	**CAP Below**	£11,950.00
Mileage	64,739 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

WARNING LIGHTS ON DASH TOW BAR, AD-BLUE.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows

Photos








MX72 VTN


TRANSIT
BASE
2.0 I4 HPCR Panther Diesel
130 PS
Stage 6.2
350L
BKRA
0.50
FORD
e1*2007/46*1096
* WF0CXXTTRCNL20558 *
3500 kg
6500 kg
1850 kg
2450 kg
W(mm)
L(mm)
a(mm)
H
3954
FED







Speedometer
Vehicle is on
64739.8 mls











Speedometer
Brake pad wear
Service now
64739.8 mls



Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Door osf
Dented
Over 30mm



3: Door osr
Dented
With Paint Damage



4: Qtr Panel osr
Rusted
Over 5mm



5: Tailgate
Dented
With Paint Damage



6: Qtr Panel nsr
Rusted
Over 5mm



7: Door nsf
Dented
With Paint Damage



8: Dash Warning Lights
Displayed
No Action
BREAK WEAR WARNING

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK