COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MX72VTM

Ford Transit 2.0 EcoBlue 130ps LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45226
Cap Code	FOTR2035331DTM2 5 L

Details

Location	Livingston	**GVW**	3500kg	**CAP Clean**	£19,200.00
Reg. date	19/10/2022	**Colour**	WHITE	**CAP Average**	£15,650.00
Year	2022	**VIN**	WF0CXXTTRCNL20557	**CAP Below**	£13,150.00
Mileage	46,970 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

WARNING LIGHTS ON DASH TOW BAR, AD-BLUE.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking


Photos









HIGHWAY MAINTENANCE
MX72 VTM

FORD
e1*2007/46*1096
* WF0CXXTTRCNL20537 *
TRANSIT
BKRA
0.50
3500
6500
2450
H 3954
FED





encon






Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Dented
Over 30mm



3: Wing osf
Dented
With Paint Damage



4: Door osf
Dented
With Paint Damage

No Image

5: Door osr
Dented
With Paint Damage



6: Qtr Panel osr
Rusted
Over 5mm



7: Tailgate
Dented
With Paint Damage



8: Qtr Panel nsr
Rusted
Over 5mm



9: Door nsr
Dented
Over 30mm



10: Door nsf
Dented
Over 30mm



11: Flasher Side Repeater ns
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK

Commercial Vehicle Auctions Limited