COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CK75EHC

Peugeot Partner 1.5 BlueHDI 100PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Code	PEPA15PP10VDTM2 6 L

Details

Location	Avonmouth	**GVW**	2390kg	**CAP Clean**	£13,600.00
Reg. date	30/09/2025	**Colour**	WHITE	**CAP Average**	£13,100.00
Year	2025	**VIN**	VR3EDYHT8SJ733951	**CAP Below**	£11,800.00
Mileage	12,788 Miles Not Warranted	**Body Style**	Fridge Van SWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	29/09/2028	**Gears**	6

WARNING LIGHT ON DASH, THERMOKING B-100 ECO UNIT, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Drivers airbag
- Cruise control
- Mobile phone App interface
- Central locking
- Rear parking sensor
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows


Photos















MAR
COOLING
SOLUTIONS




PEUGEOT



STELLANTIS AUTO SAS
VR3EDYHT8SJ733951
2390 KG
3390 KG
1 – 1200 KG
2 – 1400 KG




THERMO KING


MAR
COOLING
SOLUTIONS
MAR1255






THERMO KING
B-100 ECO


R 1 3 5
2 4 6


THERMO KING
TIME 12:13
DATE 16 Nov 2023
TRANSCAN ADVANCE
transcan
Connected Fleet Technology



THERMO KING







Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Wheel nsf
Corroded
Light



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door nsr
Chipped
Over 5mm



5: Wheel nsr
Corroded
Light



6: Bumper Rear
Scratched
Over 25mm Not Thru Paint



7: Tailgate
Dented
Over 30mm



8: Wheel osr
Corroded
Light



9: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



10: Bumper Front
Scratched
Over 100mm Thru Paint



11: Grille Front
Scratched (Painted)
Over 25mm Thru Paint



12: Wheel osf
Corroded
Light

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited