COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BT68LWO

Iveco Daily 35-120

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	38809
Cap Code	IVDA23S352VDTM2 4 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£4,875.00
Reg. date	16/01/2019	**Colour**	WHITE	**CAP Average**	£4,200.00
Year	2019	**VIN**	ZCFC1358605258979	**CAP Below**	£3,300.00
Mileage	65,703 Miles Warranted	**Body Style**	Panel Van MWB	**Gearbox**	MANUAL
		MOT Due	27/08/2027	**Gears**	6
Fuel Type	DIESEL				

AD BLUE, SIDE LOADING DOOR, 3520 WB

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos


























Commercial Vehicle Auctions Limited

Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Not Thru Paint



2: Screen Front
Chipped
Over 10mm



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




5: Door Mirror Assy nsf
Broken
Replace



6: Flasher Side Repeater ns
Broken
Replace



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
Between 10mm + 30mm



9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Door nsr
Dented
Over 2 UpTo 10mm



12: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



13: Door Mirror Assy osf
Broken
Replace



14: Steering Wheel
Damaged
Replace



15: Centre Console Front
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK