COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SJ20JJO

Renault Master 35 2.3

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Avonmouth	**Fuel Type**	DIESEL	**Body Style**	Curtainside
Reg. date	01/06/2020	**GVW**	3500kg	**MOT Due**	20/08/2027
Year	2020	**Colour**	BLUE	**Gearbox**	MANUAL
Mileage	184,031 Miles Not Warranted	**VIN**	VF6VG000764531241	**Tail Lift**	Column

AD BLUE, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- USB/iPod interface
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos









R135
246

SJ20 JJO








TRUCK CRAFT BODIES LTD
1 - 1850
2 -





Condition Check



Damage Photos



1: Roof
Cracked
Replace



2: Bonnet
Chipped
Over 5mm



3: A Post os
Missing
Replace



4: Wing nsf
Chipped
Over 5mm



5: Wing nsf
Dented
Over 30mm




6: Wheel nsf
Corroded
Light



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Dented
Over 30mm



10: Roof
Cracked
Replace



11: B Post ns
Chipped
Over 5mm




12: Wheel nsr
Corroded
Light



13: Bumper Rear
Rusted
Over 5mm



14: Wheel osr
Corroded
Light



15: B Post os
Chipped
Over 5mm



16: Roof
Cracked
Replace



17: Door osf
Chipped
Over 5mm



18: Door osf
Rusted
Over 5mm



19: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



20: Wheel osf
Corroded
Light



21: Roof
Rusted
Over 5mm



22: Wing osf
Chipped
Over 5mm



23: Sill os
Scratched
Over 25mm Thru Paint



24: Door osf
Dented
Over 30mm



25: Seat Base Cover osf
Holed
Over 3mm



26: Steering Wheel
Damaged
Replace



27: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK