COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MC73OMG

Ford Ranger WILDTRAK 2.0 ECOBLUE 205PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56276
Cap Code	FORA20WILD7DTA4 7 L

Details

Location	Doncaster	**Colour**	GREY	**CAP Average**	£19,450.00
Reg. date	30/11/2023	**VIN**	6FPPXXMJ2PPT81583	**CAP Below**	£16,750.00
Year	2023	**Body Style**	Pickup Double Cab	**Gearbox**	AUTOMATIC
Mileage	49,422 Miles Not Warranted	**Service history**	None	**Gears**	1
Fuel Type	DIESEL	**MOT Due**	29/11/2026	**Axle Combi**	4x4
GVW	3280kg	**CAP Clean**	£21,000.00		

E/MIRRORS, HEATED WINDSCREEN, AD-BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Navigation system
- Digital radio
- Metallic Paint
- Leather seat trim
- Cruise control
- Park assist camera
- Air conditioning
- Drivers airbag
- Front parking sensor
- Rear parking sensor
- Front electric windows
- Passenger airbag
- Heated front seat
- Auxiliary input socket
- Rear electric windows
- Central locking


Photos












SW
0
mph
3683.2
Miles
40
mph
29.3
mpg
0.2
gal/h
PRNDM



P
R
N
D

FORD
e5*2007/46*0080
6FPPXXMJ2PPT81583
3280 kg
6500 kg
1490 kg
1959 kg
VIN
2AB
0.50
MADE IN SOUTH AFRICA

MC73 OMG
















Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm




5: Door nsr
Scratched
Over 25mm Not Thru Paint



6: C Post ns
Dented
With Paint Damage



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Door osf
Chipped
Multiple Chips

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK