COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FL20TWZ

Daf CF 320

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster	**GVW**	26000kg	**MOT Due**	31/07/2027
Reg. date	28/08/2020	**Colour**	GREEN	**Cab Type**	DAY CAB
Year	2020	**VIN**	XLRASM4700G297000	**Gearbox**	AUTOMATIC
Mileage	206,293 Km Not Warranted	**Body Style**	Refuse Collector	**Axle Combi**	6x2
Fuel Type	DIESEL	**Service history**	None	**Rear Suspension**	Air

HILLEND ENGINEERING PLK 21 1M BODY, TERBERG SINGLE LIFT, SURROUND CAMERA SYSTEM

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim

Photos
















000km/h
0206294.0km
OK


R N D
250°



DAF TRUCKS N.V.
Type
Motor no.


WARNING
Observe gap when operating mechanism

WARNING
Observe gap when operating mechanism

DANGER KEEP OUT

FORS












Condition Check



Damage Photos




1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Panel Front
Chipped
Multiple Chips



3: Bumper Front
Dented
With Paint Damage



4: Door nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Wing nsf
Cracked
Replace



8: Door osf
Dented
Over 30mm



9: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK