COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

EJ71CJU

Ford Transit Custom 300 2.0 ECOBLUE 130PS LEADER

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	44503
Cap Code	FOTU200L3LHDTM2 1 L

Details

Location	Bedford	**GVW**	3000kg	**CAP Clean**	£8,300.00
Reg. date	13/12/2021	**Colour**	WHITE	**CAP Average**	£7,425.00
Year	2021	**VIN**	WF0YXXTTGYMG55618	**CAP Below**	£6,100.00
Mileage	73,634 Miles Not Warranted	**Body Style**	Fridge Van L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

HEAVY SMOKING, STRANGE ENGINE NOISE AD BLUE, SIDE LOADING DOOR, GAH UNIT

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Air conditioning
- Front electric windows

Photos












transcan





FORD
e1*2007/46*1005
WF0YXXTTGYMG55618
3000 kg
5240 kg
1675 kg
1590 kg
CUSTOM
BASE
W(mm)
L(mm)
a(mm)
3300
FCC











R452A












Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Wing nsf
Poor Previous Repair
Poor Colour



5: Door nsr
Dented
Over 2 UpTo 10mm



6: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



7: Bumper Reflector osr
Missing
Replace



8: Door osr
Scratched
Over 25mm Thru Paint



9: Door osr
Dented
Between 10mm + 30mm



10: Qtr Panel osr
Dented
Between 10mm + 30mm



11: Door osf
Dented
With Paint Damage



12: Fascia Trim
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK