COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO70YCH

Fiat Ducato Maxi 35 2.3 Multijet 140PS

Non Runner

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	44907
Cap Code	FIDU233MM4DDTM2 5 L

Details

Location	Avonmouth	**Colour**	WHITE	**CAP Below**	£6,025.00
Reg. date	06/11/2020	**VIN**	ZFA25000002P43517	**Gearbox**	MANUAL
Year	2020	**Body Style**	Dropside MWB	**Gears**	6
Mileage	Not Showing	**MOT Due**	Expired	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£8,575.00		
GVW	3500kg	**CAP Average**	£7,525.00		

NON-RUNNER-VARIOUS PARTS MISSING FROM ENGINE, WARNING LIGHTS ON DASH, AD BLUE, TOW BAR, E/MIRRORS, MOT SHOWS 102,289 MILES

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features



- Bluetooth connection
- USB/iPod interface
- Central locking
- Park assist camera
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos
















Condition Check



Damage Photos




1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Hole
Over 25mm



3: Wing nsf
Chipped
Over 5mm



4: Wheel nsf
Corroded
Light



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Chipped
Over 5mm



7: B Post ns
Chipped
Over 5mm



8: Qtr Panel nsr
Chipped
Over 5mm



9: Wheel nsr
Corroded
Light



10: Qtr Panel osr
Chipped
Over 5mm



11: Wheel osr
Corroded
Light




12: B Post os
Chipped
Over 5mm



13: Door osf
Chipped
Over 5mm




14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Corroded
Light



16: Wing osf
Dented
Over 30mm



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Bumper Front
Scratched
Over 100mm Thru Paint



19: Bonnet
Chipped
Over 5mm



20: Bumper Front
Hole
Over 25mm



21: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	Fault

EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault	Service indicator light illuminated	Fault