COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HT23VXR

Ford Transit 350 2.0 ECOBLUE 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	45234
Cap Code	FOTR2035331DTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**CAP Clean**	£17,200.00
Reg. date	27/07/2023	**Colour**	WHITE	**CAP Average**	£15,950.00
Year	2023	**VIN**	WF0CXXTTRCPL52169	**CAP Below**	£13,750.00
Mileage	51,480 Miles Not Warranted	**Body Style**	Tipper Double Cab	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	05/08/2027	**Gears**	6

TOW BAR, AD BLUE

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Front electric windows

Photos











HIGHWAY MAINTENANCE


UK
NI
TRANSIT
BASE
2.0 l HPCR Panther Diesel
130 PS
Stage 6.2
350L
BKRA
0.50
FORD
W(mm)
L(mm)
H
3954
FED








EMERGENCY
ON
Raise
Lower
Isolation switch
ON














Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Panel Front
Scratched
UpTo 25mm Not Thru Paint



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Fuel Flap
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door nsr
Dented
Between 10mm + 30mm



13: Door osr
Scratched
Over 25mm Not Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



16: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK