COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

SV22UGO

Renault Master 35 2.3

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	RTMA2345C3BDTM2 3 L

Details

Location	Avonmouth	**GVW**	3500kg	**Gearbox**	MANUAL
Reg. date	12/05/2022	**Colour**	BLACK	**Gears**	6
Year	2022	**VIN**	VF6VG000368790852	**Tail Lift**	Column
Mileage	83,642 Miles Not Warranted	**Body Style**	Curtainside L3		
		MOT Due	06/01/2027		
Fuel Type	DIESEL				

NEW BATTERTY FITTED AD BLUE, HEATED WINDSCREEN, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- USB/iPod interface
- Central locking
- Cruise control
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag

Photos










TRUCK CRAFT BODIES LTD
g11*2018/858*00125*00
STAGE 2
VF6VG000368790852
3500 KG
1 - 1850 KG
2 - 2800 KG
3 - KG
4 - KG
Stephanie Works
Bayley Street
SK15 1PY
www.truckcraftbodies.co.uk
+44 (0)1613049404
UK
NI


UK
NI


DEL





R135
LH
246





Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm




2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Over 5mm



4: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Corroded
Light



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Chipped
Over 5mm



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel osr
Chipped
Over 5mm



12: Wheel osr
Corroded
Light



13: Wheel osf
Corroded
Light



14: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



15: Door osf
Scratched
Over 25mm Thru Paint



16: Seat Back Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK