COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YL69FPO

RENAULT TRAFIC SL28 ENERGY DCI 120PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	45100
Cap Code	R1TR20S82PVDTM2 5 L

Details

Location	Doncaster	**GVW**	2935kg	**CAP Clean**	£3,600.00
Reg. date	31/12/2019	**Colour**	WHITE	**CAP Average**	£3,100.00
Year	2019	**VIN**	VF1FL000X64765511	**CAP Below**	£2,425.00
Mileage	164,780 Miles Warranted	**Body Style**	Panel Van SWB	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

COLLECTED AS NON-RUNNER-INJECTOR, EGR & BATTERY FAULTS, WARNING LIGHTS ON DASH, AD BLUE, SIDE LOAD DOOR, TOW BAR, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Air conditioning
- Cloth seat trim
- Auxiliary input socket
- Front electric windows
- Digital radio
- Drivers airbag
- USB/iPod interface
- Central locking


Photos








RENAULT
Trafic Van
RENAULT


UNIROYAL



205/65 R 16

Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Bumper Front
Chipped
Over 5mm



4: Wheel nsf
Corroded
Light



5: Wing nsf
Chipped
Over 5mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsf
Chipped
Over 5mm



9: Door nsr
Chipped
Over 5mm



10: Qtr Panel nsr
Chipped
Over 5mm



11: Qtr Panel nsr
Chipped
Over 5mm



12: Bumper Rear
Chipped
Over 5mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Wheel nsr
Corroded
Light



15: Tailgate
Chipped
Over 5mm



16: Tailgate
Scratched
Over 25mm Thru Paint



17: Tailgate
Scratched
Over 25mm Thru Paint



18: Bumper Rear
Scratched
Over 100mm Thru Paint



19: Wheel osr
Corroded
Light



20: Qtr Panel osr
Chipped
Over 5mm



21: Door osf
Chipped
Edge Chip



22: Door osf
Chipped
Over 5mm



23: Wheel osf
Corroded
Light



24: Handle Outer osf
Scratched (Painted)
Over 25mm Thru Paint



25: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



26: Wing osf
Chipped
Over 5mm



27: A Post os
Chipped
Over 5mm



28: Bumper Front
Chipped
Over 5mm




29: Bonnet
Dented
Over 30mm



30: Seat Base Cover osf
Torn
Over 3mm



31: Carpets Front
Holed
Over 3mm



32: Seat Base Cover nsf
Soiled
Light

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK