COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YD68ZCA

Volkswagen Crafter CR35 2.0 TDI 140PS STARTLINE

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	44021
Cap Code	VWCR205L4SLDTM2 1 L

Details

Location	Avonmouth
Reg. date	04/10/2018
Year	2018
Mileage	105,628 Miles Not Warranted
Fuel Type	DIESEL
GVW	3500kg
Colour	WHITE

VIN	WV3ZZZSZZJ9041784
Body Style	Luton LWB
Service history	Yes
Service documents	Printout
Last service date	07/11/2024
Last service miles	94,749
MOT Due	01/12/2026

CAP Clean	£16,850.00
CAP Average	£14,550.00
CAP Below	£11,350.00
Gearbox	MANUAL
Gears	6
Tail Lift	Column

WARNING LIGHT ON DASH, AD BLUE, TOW BAR

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features


- Bluetooth connection
- Front electric windows
- Auxiliary input socket
- Drivers airbag
- Radio/CD
- Central locking
- USB/iPod interface
- Cloth seat trim

Photos














VOLKSWAGEN AG
WV3ZZZSZZJ9041784
3500 kg
6000 kg
1- 1800 kg
2- 2100 kg
Typ SZN1E



DEL
RAISE
LOWER






ALLOY BODIES LTD
e11*NKS*4335
STAGE 2
WV3ZZZSZZ59041784






Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Wing nsf
Dented
Over 30mm



6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsf
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Door osf
Chipped
Multiple Chips



10: B Post os
Scratched
Over 25mm Thru Paint



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Bumper Front
Scratched
Over 100mm Thru Paint



13: Seat Base Cover osf
Holed
Over 3mm



14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault