COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE65UYZ

Daf LF 220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Avonmouth
Reg. date	16/10/2015
Year	2015
Mileage	594,637 Km Warranted
Fuel Type	DIESEL
GVW	18000kg
Colour	RED

VIN	XLRAEL3700L448243
Body Style	Box Van
Service history	Yes
Service documents	Printout
Last service date	15/07/2025
Last service miles	524,107
MOT Due	31/05/2027

Cab Type	DAY CAB
Gearbox	AUTOMATIC
Axle Combi	4x2
Rear Suspension	Steel
Tail Lift	Cantilever

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Auxiliary input socket
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows

Photos



















Driver & Vehicle Standards Agency
Plate
PE65UYZ
XLRAEL3700L448243
DAF /LF 220 FA
RIGID R
16/10/15
2015
18000
19000
19000
500
11500
DEPARTMENT FOR TRANSPORT
17/05/16
GREAT BRITAIN
REPLACEMENT


DAF TRUCKS N.V.
XLRAEL3700L448243
GB
18000
19000
18000
19000
7500
7500
11500
11500
D-1,5 %
TYPE
LEN
9700
2550





UP
CLOSE
OPEN
DOWN








DAF


R
N
D












Condition Check



Damage Photos



1: Panel Front
Chipped
Over 5mm



2: Wing nsf
Scratched
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Corroded
Light



5: Qtr Panel nsr
Chipped
Over 5mm



6: Qtr Panel nsr
Chipped
Over 5mm



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Wheel nsr
Corroded
Light



9: Qtr Panel nsr
Chipped
Over 5mm



10: Tailgate
Rusted
Over 5mm



11: Tailgate
Rusted
Over 5mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Chipped
Over 5mm



14: Wheel osr
Corroded
Light



15: Qtr Panel osr
Hole
Over 10mm



16: Qtr Panel osr
Scratched
Over 25mm Thru Paint



17: Qtr Panel osr
Chipped
Over 5mm



18: Qtr Panel osr
Chipped
Over 5mm



19: Door osf
Chipped
Over 5mm



20: Wheel osf
Corroded
Light




21: Wing osf
Scratched
Over 25mm Thru Paint



22: Panel Front
Chipped
Over 5mm



23: Grille Front
Broken
Replace



24: Seat Base Cover osf
Holed
Over 3mm



25: Centre Console Front
Holed
Over 3mm



26: Centre Console Front
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK