COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MC73OMJ

Ford Ranger WILDTRAK 2.0 ECOBLUE 205PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56276
Cap Code	FORA20WILD7DTA4 7 L

Details

Location	Bedford	**Colour**	GREY	**CAP Below**	£18,400.00
Reg. date	30/11/2023	**VIN**	6FPPXXMJ2PPT81575	**Gearbox**	AUTOMATIC
Year	2023	**Body Style**	Pickup Double Cab	**Gears**	1
Mileage	34,693 Miles Not Warranted	**MOT Due**	29/11/2026	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£23,100.00		
GVW	3280kg	**CAP Average**	£21,350.00		

AD BLUE, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Rear electric windows
- Rear parking sensor
- Leather seat trim
- Air conditioning

Photos





WILDTRAK




FORD
e5*2007/46*0080
6FPPXXMJ2PPT81575
3280 kg
6500 kg
1490 kg
1959 kg
2AB
0.50
VIN
MADE IN SOUTH AFRICA




MC73 OMJ










RANGER
MC73 OMJ
















Condition Check



Damage Photos



1: Wheel osf
Scratched
Up To 50mm



2: Bonnet
Chipped
1 To 5



3: Wheel nsf
Scratched
Up To 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Up To 50mm



7: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



8: Door osr
Chipped
1 To 5



9: Door osf
Chipped
Edge Chip



10: Door nsf
Chipped
Edge Chip



11: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Not Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK