COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

WP18BLJ

Vauxhall Corsa 1.3 CDTi 16V 95PS ECOTEC

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	41923
Cap Code	VACS129ESSVDTM2 5 L

Details

Location	Doncaster	**Colour**	WHITE	**CAP Average**	£2,825.00
Reg. date	12/06/2018	**VIN**	W0V0XEP05J4304676	**CAP Below**	£2,150.00
Year	2018	**Body Style**	Car Derived Van	**Gearbox**	MANUAL
Mileage	64,168 Miles Warranted	**Service history**	None	**Gears**	5
Fuel Type	DIESEL	**MOT Due**	11/06/2027		
GVW	1710kg	**CAP Clean**	£3,325.00		

COLLECTED AS A NON-RUNNER - TYERS WORN, FUEL PUMP LEAKING E/MIRRORS, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos









Eco Index
67.8 mpg
64168 mi


OPEL
WOV0XEP05J4304676
1710 kg
2900 kg
1-0920 kg
2-0820 kg
0,50
70 kW






Eco Index
67.8 mpg
64168 mi



WP18 BLJ







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Bumper Rear
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	Yes

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK