COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO21ZCK

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	43038
Cap Code	MESP213L34BDTM2 5 L

Details

Location	Bedford	**GVW**	3500kg	**Gearbox**	MANUAL
Reg. date	31/03/2021	**Colour**	WHITE	**Gears**	6
Year	2021	**VIN**	W1V9071352N100880	**Tail Lift**	Column
Mileage	208,663 Miles Warranted	**Body Style**	Dropside L3		
		MOT Due	03/04/2027		
Fuel Type	DIESEL				

AD BLUE, TAIL LIFT TESTED 23/07/2026

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Park assist camera
- Air conditioning
- Front electric windows

Photos




























Commercial Vehicle Auctions Limited

Condition Check



Damage Photos



1: Wing osf
Dented
Over 2 UpTo 10mm



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bonnet
Chipped
1 To 5



4: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Flasher Side Repeater ns
Broken
Replace



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



11: Flasher Side Repeater os
Broken
Replace



12: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK