COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE63NVN

Daf LF 55.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Avonmouth
Reg. date	01/12/2013
Year	2013
Mileage	1,081,592 Km Warranted
Fuel Type	DIESEL
GVW	18000kg
Colour	RED

VIN	XLRAE55GF0L433763
Body Style	Box Van
Service history	Yes
Service documents	Printout
Last service date	02/09/2025
Last service miles	1,014,514
MOT Due	31/10/2027

Cab Type	DAY CAB
Gearbox	AUTOMATIC
Axle Combi	4x2
Rear Suspension	Steel
Tail Lift	Cantilever

WARNING LIGHT ON DASH

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows

Photos












15 08 0km/h
81593.0km





Plate
DAF DAF FA LF55
RIGID
01/12/13
2013
12000
2600
18000
7100
11500
DEPARTMENT FOR
29/04/14
TRANSPORT
GREAT BRITAIN


DAF
DAF TRUCKS N.V.
E11 24R-032270
Cummins ISB6.7E5
DAF ID. GR 165 U1
DAF









CHASSIS No.: L433763
BUILD DATE: 06/12/13
DAF










Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Bumper Front
Cracked
Over 25mm



4: Door nsf
Chipped
Multiple Chips




5: Qtr Panel nsr
Poor Previous Repair
Poor Paint



6: Door osf
Chipped
Multiple Chips



7: Door osf
Scratched
Over 25mm Thru Paint



8: Moulding osf Wing
Scratched (Painted)
Over 25mm Thru Paint



9: Bumper Front
Insecure
Action Required



10: Switches And Controls
Missing
Replace



11: Fascia Trim
Missing
Replace



12: In Car Entertainment
Broken
Replace



13: Centre Console Front
Holed
Over 3mm



14: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
Brakes	OK		
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		