COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE64EYP

Daf LF 220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Avonmouth
Reg. date	11/09/2014
Year	2014
Mileage	714,341 Km Warranted
Fuel Type	DIESEL
GVW	18000kg
Colour	RED

VIN	XLRAEL3700L438171
Body Style	Box Van
Service history	Yes
Service documents	Printout
Last service date	17/07/2025
Last service miles	610,368
MOT Due	30/04/2027

Cab Type	DAY CAB
Gearbox	AUTOMATIC
Axle Combi	4x2
Rear Suspension	Steel
Tail Lift	Cantilever

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Auxiliary input socket
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows

Photos

















0 0km/h
342.1km
OK


Vehicle Identification No.
YT RAEL3700L438171
DAF /LF220 FA
RIGID
11/09/14
2540
18000
18000
7100
11500
DEPARTMENT FOR
09/01/15
TRANSPORT
GREAT BRITAIN
REPLACEMENT

DAF TRUCKS N.V.
D-1,5 %
TYPE
UK
18000
18000
7100
11500
DAF


UP
CLOSE
OPEN
DOWN




DAF


R
N
D








Condition Check



Damage Photos



1: Panel Front
Chipped
Over 5mm



2: Wing nsf
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Corroded
Light



6: Door nsf
Chipped
Over 5mm



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Chipped
Over 5mm



9: Qtr Panel nsr
Chipped
Over 5mm



10: Wheel nsr
Corroded
Light



11: Qtr Panel nsr
Chipped
Over 5mm



12: Tailgate
Rusted
Over 5mm



13: Tailgate
Chipped
Over 5mm



14: Tailgate
Rusted
Over 5mm



15: Qtr Panel osr
Chipped
Over 5mm



16: Wheel osr
Corroded
Light



17: Qtr Panel osr
Chipped
Over 5mm



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Chipped
Over 5mm



20: Wheel osf
Corroded
Light



21: Door osf
Chipped
Over 5mm



22: Door osf
Scratched
Over 25mm Thru Paint



23: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



24: Door osf
Scratched
Over 25mm Thru Paint



25: Wing osf
Scratched
Over 25mm Thru Paint



26: Panel Front
Chipped
Over 5mm



27: Panel Front
Cracked
Replace



28: Centre Console Front
Holed
Over 3mm



29: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited