COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

GJ65ZXC

Mercedes-Benz Actros 1824

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	**GVW**	18000kg	**Gearbox**	AUTOMATIC
Reg. date	27/11/2015	**Colour**	BLUE	**Axle Combi**	4x2
Year	2015	**VIN**	WDB9630032L955289	**Rear Suspension**	Air
Mileage	688,385 Km Not Warranted	**Body Style**	Curtainside	**Rear Doors**	Barn
Fuel Type	DIESEL	**Cab Type**	STREAMSPACE CAB (2.3M, 320MM)	**Tail Lift**	Tuckaway

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**


Features

- Air conditioning

Photos












VDO
16 42 0 0km/h
688385.5km
OK
1
2


MERCEDES IACTROS
RIGID R
27/11/15
11215
3540
18000
18000
8000
8000
11500
11500
DEPARTMENT FOR
TRANSPORT
GREAT BRITAIN
REPLACEMENT


Mercedes-Benz
DAIMLER AG
e1*2007/46*0726
WDB9630032L955289
18000 kg
32000 kg
1- 8000 kg
2- 11500 kg
3- XXXXX kg
4- XXXXX kg
T- XXXXX kg
Made in Germany




M2
M1
STOP
















Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bumper Front
Dented
Between 10mm + 30mm



3: Fog Lamp Surround os
Scratched (Painted)
UpTo 25mm Thru Paint



4: Bonnet
Chipped
Multiple Chips



5: Bumper Front
Cracked
UpTo 25mm



6: Wing nsf
Poor Previous Repair
Poor Paint



7: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



8: Door Mirror Assy nsf
Broken
Replace



9: Qtr Panel nsr
Dented
Over 30mm



10: Qtr Panel osr
Dented
Over 30mm



11: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



12: Door Mirror Assy osf
Broken
Replace



13: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK