COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PO70YAV

Fiat Ducato 35 2.3 MULTIJET 140PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44906
Cap Code	FIDU233MM4BDTM2 5 L

Details

Location	Bedford	**Colour**	WHITE	**CAP Below**	£2,625.00
Reg. date	03/09/2020	**VIN**	ZFA25000002P00721	**Gearbox**	MANUAL
Year	2020	**Body Style**	Dropside MWB	**Gears**	6
Mileage	137,627 Miles Warranted	**MOT Due**	02/09/2027	**Tail Lift**	Column
Fuel Type	DIESEL	**CAP Clean**	£3,725.00		
GVW	3500kg	**CAP Average**	£3,250.00		

ENGINE ISSUES, O/S FRONT BALL JOINT NEEDS REPLACING E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features



- Park assist camera
- Air conditioning
- Front electric windows

Photos







HIGHWAY
MAINTENANCE
P070 YAV



FCA ITALY S.P.A.
ZFA250000-02P00721
3500 KG
6500 KG
2100 KG
2400 KG
MOTORE F1AGL411B
VERSIONE 250DENAU GE
MADE IN ITALY



Wed 18 Nov
10:48






Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Grille Front
Scuffed (Unpainted)
Over 100mm



6: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



7: Wing nsf
Dented
With Paint Damage



8: Door Mirror Assy nsf
Broken
Replace



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



14: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK