COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE17HPL

Daf CF 440

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	**Colour**	RED	**Gearbox**	AUTOMATIC
Reg. date	08/03/2017	**VIN**	XLRTGM4100G149795	**Axle Combi**	6x2
Year	2017	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Mileage	868,752 Km Warranted	**Service history**	Yes	**Rear Suspension**	Air
Fuel Type	DIESEL	**MOT Due**	28/02/2027		
GVW	44000kg	**Cab Type**	SLEEPER CAB		

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Air conditioning
- Front electric windows

Photos


















VDO
12:45
0km/h
868752.8km
OK


PE17 HPL
DAF
DAF

REPLACEMENT

DAF TRUCKS N.V.
ADR4
E4
Type





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
Over 10mm



5: Wing nsf
Chipped
Multiple Chips



6: Door Mirror Assy nsf
Broken
Replace



7: Door nsf
Dented
Between 10mm + 30mm



8: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




10: Qtr Panel Arch Extension ns
Missing
Replace



11: Door osf
Scratched
Over 25mm Thru Paint



12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Wing Front Arch Extension os
Scuffed (Unpainted)
UpTo 100mm



14: Door osf
Chipped
Edge Chip



15: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK