COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE17HSZ

Daf CF 440

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	**GVW**	44000kg	**Cab Type**	SLEEPER CAB
Reg. date	14/03/2017	**Colour**	RED	**Gearbox**	AUTOMATIC
Year	2017	**VIN**	XLRTGM4100G150837	**Axle Combi**	6x2
Mileage	1,307,216 Km Warranted	**Body Style**	Tractor Unit	**Steering Combi**	Mid-Lift
Fuel Type	DIESEL	**MOT Due**	30/04/2027	**Rear Suspension**	Air

WARNING LIGHTS ON DASH

Tyres


NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Air conditioning

Photos













Check manual entry before confirmation
OK

PE17 HSZ
DAF
DAF



DAF TRUCKS N.V.
GB
23700 kg
44000 kg
1 - 8000 kg
2 - 7500 kg
3 - 11500 kg
4 - kg
T - 19000 kg
27000 kg
44000 kg
1 - 8000 kg
2 - 7500 kg
3 - 11500 kg
4 - kg
T - 19000 kg


BRIDGES






Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Fog Lamp Surround os
Scratched (Painted)
Over 25mm Thru Paint



3: Bumper Front
Chipped
Multiple Chips



4: Panel Front
Chipped
Multiple Chips



5: Screen Front
Chipped
Over 10mm



6: Fog Lamp Surround ns
Scratched (Painted)
UpTo 25mm Thru Paint



7: Wing nsf
Scratched
UpTo 25mm Thru Paint



8: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



9: Door nsf
Scratched
Over 25mm Thru Paint



10: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



11: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm



12: Door Mirror Assy osf
Broken
Replace



13: Door osf
Scratched
UpTo 25mm Thru Paint



14: In Car Entertainment
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK