COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

YH20LPN

Ford Transit Connect 240 1.5 ECOBLUE 100PS

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	42555
Cap Code	FOTC154L10VDTM2 3 L

Details

Location	Bedford	**GVW**	2405kg	**CAP Clean**	£6,975.00
Reg. date	25/03/2020	**Colour**	WHITE	**CAP Average**	£6,150.00
Year	2020	**VIN**	WF0SXXWPGSLB01086	**CAP Below**	£4,925.00
Mileage	45,372 Miles Warranted	**Body Style**	Panel Van L2	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	12/02/2027	**Gears**	6

AD BLUE, TWIN SIDE LOADING DOORS, E/MIRRORS

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Front parking sensor
- Front electric windows
- Park assist camera
- Rear parking sensor
- Air conditioning

Photos














FORD
e1*2007/46*0272
WF0SXXWPGSLB01086
2405 kg
3500 kg
1225 kg
1250 kg
PU2
Base H.P.
1.5L DVNEO TC DSL B
STG 6.2 EMISS





Speedometer
0 mph
45373.2 mls


Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
Over 10mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



9: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



10: Door osr
Dented
With Paint Damage

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK