COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE63NVO

Daf LF 55.220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Doncaster
Reg. date	01/12/2013
Year	2013
Mileage	1,205,581 Km Warranted
Fuel Type	DIESEL
GVW	18000kg
Colour	RED

VIN	XLRAE55GF0L433762
Body Style	Box Van
Service history	Yes
Service documents	Printout
Last service date	09/02/2026
Last service miles	1,265,578
MOT Due	31/12/2026

Cab Type	DAY CAB
Gearbox	AUTOMATIC
Axle Combi	4x2
Rear Suspension	Steel
Rear Doors	Roller
Tail Lift	Cantilever

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**

Features

- Cruise control
- Front electric windows
- Auxiliary input socket
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos













14:11 0 .0km/h
205882.2km 0
1
2
OK

N
M/A

DEPARTMENT FOR
TRANSPORT
GREAT BRITAIN


DAF
DAF TRUCKS N.V.
Cummins ISB6.7E5
DAF ID. GK 165 UI

WHEEL
TORQUE
700 N/M
125 PSI







PE63 NVO






Condition Check



Damage Photos



1: Panel Front
Cracked
Replace



2: Panel Front
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel osr
Scratched
Over 25mm Thru Paint



6: Door osf
Dented
With Paint Damage



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition	OK	**Upholstery Condition**	Poor
Seat Condition	OK	**Odour**	-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK