COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE65UZA

Daf LF 220

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Avonmouth	**GVW**	18000kg	**Cab Type**	DAY CAB
Reg. date	16/10/2015	**Colour**	RED	**Gearbox**	AUTOMATIC
Year	2015	**VIN**	XLRAEL3700L448242	**Axle Combi**	4x2
Mileage	681,138 Km Warranted	**Body Style**	Box Van	**Rear Suspension**	Steel
Fuel Type	DIESEL	**MOT Due**	31/08/2027	**Tail Lift**	Cantilever

Tyres

NSF	**NSI1**	**NSI2**	**NSI3**	**NSI4**
OSF	**OSI1**	**OSI2**	**OSI3**	**OSI4**
Spare	**NSO1**	**NSO2**	**NSO3**	**NSO4**
	OSO1	**OSO2**	**OSO3**	**OSO4**


Features

- Auxiliary input socket
- Drivers airbag
- Radio/CD
- Central locking
- Air conditioning
- Cloth seat trim
- Front electric windows


Photos












0km/h
138.5km
OK
2


Plate
PE65UZA
XLRAEL4700L448242
DAF /LF 220 FA
RIGID R
16/10/15
2015
18000
19000
7500
11500
DEPARTMENT FOR
TRANSPORT
GREAT BRITAIN
REPLACEMENT


DAF TRUCKS N.V.
-1,5 %
TYPE
18000
11500
DAF








DAF

R
N
D


Condition Check



Damage Photos



1: Panel Front
Chipped
Over 5mm



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Corroded
Light



5: Door nsf
Chipped
Over 5mm



6: Door nsf
Chipped
Edge Chip



7: Qtr Panel nsr
Chipped
Over 5mm



8: Qtr Panel nsr
Chipped
Over 5mm



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Chipped
Over 5mm



11: Tailgate
Rusted
Over 5mm



12: Tailgate
Chipped
Over 5mm



13: Tailgate
Rusted
Over 5mm



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Qtr Panel osr
Chipped
Over 5mm



16: Wheel osr
Corroded
Light



17: Qtr Panel osr
Chipped
Over 5mm



18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Thru Paint



20: Wheel osf
Corroded
Light



21: Door osf
Chipped
Edge Chip




22: Qtr Panel osr
Chipped
Over 5mm



23: Door osf
Scratched
Over 25mm Thru Paint



24: Door Mirror Assy osf
Broken
Replace



25: Wing osf
Chipped
Over 5mm



26: Bumper Front
Scratched
Over 100mm Thru Paint



27: Panel Front
Chipped
Over 5mm



28: Door Mirror Assy nsf
Broken
Replace



29: Qtr Panel osr
Chipped
Over 5mm



30: Centre Console Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK

Commercial Vehicle Auctions Limited