COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CA18EFG

Ford Tourneo Custom 320 2.0 EcoBlue 130PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	42086
Cap Code	FOCT20232ZYDTM2 1 L

Details

Location	Avonmouth	**Colour**	GREY	**CAP Below**	£8,175.00
Reg. date	11/06/2018	**VIN**	WF03XXTTG3JJ89924	**Gearbox**	MANUAL
Year	2018	**Body Style**	Minibus	**Gears**	6
Mileage	64,859 Miles Warranted	**MOT Due**	17/09/2027	**Doors**	4
Fuel Type	DIESEL	**CAP Clean**	£12,700.00		
GVW	3190kg	**CAP Average**	£10,750.00		

8 SEATER, TWIN SIDE LOAD DOOR, TOW BAR, ALLOY WHEELS, E/MIRRORS, HEATED WINDSCREEN

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Bluetooth connection
- Rear parking sensor
- Air conditioning
- Central locking
- Cruise control
- Auxiliary input socket
- Front electric windows
- Cloth seat trim
- Front parking sensor
- Digital radio
- Drivers airbag
- Heated front seat
- Mobile phone App interface
- Passenger airbag






Photos








Speedometer
0 mph
64859.7 mls




FORD
CUSTOM
TREND
PANTHER 200 Diesel
130PS
320L
ST6 6
YMFS
0.50
3CK
MG
AA
V6
3190
5240
1725
1640
FAC








Ford
AIRBAG

R 1 3 5
2 4 6






Condition Check



Damage Photos



1: Screen Front
Chipped
Over 10mm



2: Bonnet
Chipped
Over 5mm



3: Wing nsf
Chipped
Over 5mm



4: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Chipped
Over 5mm



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



8: Tailgate
Scratched
Over 25mm Not Thru Paint



9: Tailgate
Scratched
Over 25mm Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Door osr
Scratched
Over 25mm Thru Paint



12: Sill os
Chipped
Over 5mm



13: Door osf
Scratched
Over 25mm Thru Paint



14: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Bumper Front
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
Edge Chip



18: Handle Outer nsr
Scratched (Painted)
Over 25mm Thru Paint



19: Fuel Flap
Scratched
Over 25mm Thru Paint



20: Bumper Front
Scratched
Over 100mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK