COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BK72OZR

Nissan Primastar 28 2.0 DCI 110ps Acenta

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	54267
Cap Code	NIPR202LA1VDTM2 3 L

Details

Location	Livingston	**GVW**	2800kg	**CAP Clean**	£10,950.00
Reg. date	30/09/2022	**Colour**	WHITE	**CAP Average**	£9,975.00
Year	2022	**VIN**	VNVF4000069834749	**CAP Below**	£8,350.00
Mileage	63,461 Miles Not Warranted	**Body Style**	Crew Van L1	**Gearbox**	MANUAL
Fuel Type	DIESEL	**MOT Due**	Expired	**Gears**	6

WARNING LIGHTS ON DASH SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres


NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Rear parking sensor

Photos








NISSAN AUTOMOTIVE EUROPE S.A.S.
YWYF4000069834749
2800 Kg
4800 Kg
1- 1625 Kg
2- 1650 Kg
8 Rue Jean Pierre Timbaud
78180 Montigny-Le-Bretonneux France









Check
Parking sensors

Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint



4: Bumper Rear
Scratched
25 to 100mm Thru Paint



5: Tailgate
Chipped
Multiple Chips



6: Door nsf
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault