COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

HV74PLO

Ford Ranger WILDTRAK 2.0 ECOBLUE 205PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56276
Cap Code	FORA20WILD7DTA4 7 L

Details

Location	Bedford
Reg. date	30/09/2024
Year	2024
Mileage	43,748 Miles Not Warranted
Fuel Type	DIESEL
GVW	3280kg

Colour	SILVER
VIN	6FPPXXMJ2PRK22519
Body Style	Pickup Double Cab
MOT Due	29/09/2027
CAP Clean	£23,350.00
CAP Average	£22,000.00

CAP Below	£19,400.00
Gearbox	AUTOMATIC
Gears	1
Axle Combi	4x4

AD BLUE, TOW BAR, E/MIRRORS, ALLOY WHEELS

Tyres



NSF	
NSR	
OSF	
OSR	
Spare	


Features

- Front parking sensor
- Rear parking sensor
- Heated front seat
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Leather seat trim

Photos







WILDTRAK





FORD
e5*2007/46*0080
6FPPXXMJ2PRK22519
3280 kg
6500 kg
1490 kg
1959 kg
2AB
0.50
VIN
MADE IN SOUTH AFRICA










TERRITORY A/T




GOODYEAR


TERRITORY













Condition Check



Damage Photos



1: Wheel nsr
Scratched
Over 50mm



2: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Number Plate Rear
Broken
Replace



5: Bumper Rear
Scratched
Up To 25mm Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK